

**INTERNATIONAL ROAD DYNAMICS INC.**

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Phone (306) 653-6600 Fax: (306) 242-5599

- Site Service Report**July 28, 2010****IRD SO#: 11167****IRD Ref:****From: Brent Eckhart****To:****Project Name: Danville LTPP****Project Location: RT 29 Southbound****Service Date(s): 7-28-2010****Weather: Clear and hot****Job Description:****Perform bi-annual site inspection and electrical measurements****Work Completed:****Inspected cabinet, sensor and junction box locations.****Sensors look and sound good. Bolts are sealed with silicon and pads don't have any visible damage. Loops are in good condition and all sensor home runs appear to be in good condition.****Concrete around pads and loops do have hairline cracks. Has not appeared to get worse since my last inspection. Not a matter of concern.****Grass in the cabinet and junction box area is getting a little long, especially in median, but boxes are still visible and have a good seal.****Removed any visible dust from inside of the cabinet.****Performed electrical readings.****Ensured tight terminations on most of the sensor and electronic power inputs.****Once site and electrical inspection was completed I had IRD Tier 1 support dial in to verify operation of the onsite modem and phone line. Support also confirmed vehicle records and configurations looked good prior to me leaving site.****Work Remaining:****N/A****Parts Used:****N/A****Mileage / Travel Time:****4hrs****Time Spent on Site:****2hrs****Notes:****Action Items:**

Item	Action Required	Ownership
1.		